



TOYOTA

BORNEO MOBILITY (SARAWAK) SDN. BHD. (1360430-M)
SST REGISTRATION NO. Y60-2003-32000002

REPAIR ESTIMATE

Page: 1

Owner's Name and Address 8573808
PERBADANAN PRODUKTIVITI MALAYSIA (MA439959
LOT 894, LORONG DEMAK LAUT 3A 439960
TAMAN PERINDUSTRIAN DEMAK LAUT
KUCHING
93050

TOYOTA FORTUNER 2.7V (P) A/T
TGN51R-NKPSKEFJ
QAA7934F
PN111NV5107009861
2TR7517323
SILVER METALLIC

Date : 16/03/2021

No : 3590021304

~~Quotation Valid for 14 days~~

31/05/2013

BORNEO MOBILITY (SARAWAK) SDN
LOT 310, JALAN PENDING,
93450 KUCHING,
93450 SARAWAK
359 Tel No: 082-336743

SPARE PARTS
Disc

CUSTOMER REQUEST	JOB DESCRIPTION	LABOUR	QTY	LIST PRICE	%	NET PRICE
	MZ2008 REPLACE WIPER RUBBER	13.00				
<i>wiper rubber</i>	WIPER RUBBER RH-1877	1		20.00	05	19.00
	RUBBER WIPER LH-878	1		8.60	05	8.17
	47399 OTHERS - DISC BRAKE	65.00				
<i>front brake pad</i>	PAD KIT, FR DISC BRA	1		298.90	05	283.96
	12099 OTHERS - ENGINE ASSEMBLY	195.00				
<i>engine valve</i>	GASKET CYLINDER HEAD	1		117.10	05	111.25
<i>cover oil leak</i>	GASKET CYL HD COVER	1		66.50	05	63.18

TOTAL AMOUNT(EXCLUDING TAX)
SERVICE TAX @ 6%
TOTAL AMOUNT PAYABLE(INCLUSIVE OF TAX)



758.56
16.38
774.94