



 TOYOTA

BORNEO MOBILITY (SARAWAK) SDN. BHD. (1360430-M)

Lot 310, Jalan Pending, 93450 Kuching, Sarawak, Malaysia.

Est 1973, Salak Tinggang, 88400 Kuching, Sarawak, Malaysia
Tel: +6082-336 743 Fax: +6082-330 284 web: www.toyota.com.my

GST REGISTRATION NO 001560545280

OWNER : PERBADANAN PRODUKTIVITI MALAYSIA (MALAYSIA PRODUCTIVITY CORPORATION)
REGN NO : QAA7934F
MODEL : TGN51R-NKPSKEFJ TOYOTA FORTUNER 2.7V (P) A/T
MILAGE : 142000 KM
DATE : 11/03/2021
TEL : 082-439959 FAX : 082-439969
ATTN : MR.OSMAN EMAIL :OSMAN@MPC.GOV.MY / NORZIAH@MPC.GOV.MY

During the inspection of your car, the followings are noted :

SPARE PARTS:

OTY

RM

1	GASKET	1	2.66
2	OIL FILTER	1	34.77
3	WINDOW WASHER 30ML	1	2.57
4	FULL SYN SN 4L	1	227.91
5	FULL SYN SN 1L	2	120.46
6	PETROL INJ CLEANER	1	51.30
7	BATTERY WATER	1	1.90
8	PETROL E/G FLUSH ADT	1	42.96

A/COND SERVICE P1 460.00

TOTAL PARTS 484.53

TOTAL LABOUR 149.50

TOTAL LABOUR TAX 8.97

TOTAL ESTIMATED COST

REMARKS : Parts are subjected to change according to Company new adjustments.

** This is an estimated cost. Should there be any additional parts found

defective during the course of repair / diagnose, we will inform you

accordingly for additional supplementary cost.

We suggest that this is to be attended to the time most convenient to you. Hope to hear from you soon.
Thank you.

Yours sincerely

Prepared by: CHUNG J.S
010-5353668

