



SERVICE REPORT

No. 10180

SERVICE AGREEMENT NO.

CUSTOMER NAME

DATE

WORK ORDER NO.

WORK LOCATION

TYPE OF SERVICE

TYPE OF EQUIPMENT

MPC
PETALING JAYA,
SELANGOR DARUL EHSAN.

Routine Maintenance

☐

Rac

☐

Pump

☐

Breakdown

☐

Split Unit

☐

Cooling Tower

☐

Repair

☐

Packaged Unit

☐

Chiller

☐

Others

AHU

☐

Others

☐

MODEL

SERIAL NO

LOCATION

1

2

3

4

SERVICE DETAIL CHECKLIST

CHECK

- 1 REFRIGERANT LEAK
- 2 OIL LEVEL
- 3 LIQUIDLINE SIGHT GLASS
- 4 OPERATING PRESSURE
- 5 OPERATING TEMPERATURE
- 6 CONTROLS - ADJUST
- 7 OIL PUMP MOTOR, STARTER
- 8 MOTOR WINDING - INSULATION
- 9 STARTER - CLEAN CONTACTS
- 10 SAFETY CONTROLS - ADJUST
- 11 CONDENSER COIL - CLEAN
- 12 CONDENSER COIL - DIRTY
- 13 CONDENSER TUBES - BRUSH CLEAN
- 14 CONDENSER TUBES - CHEMICAL CLEAN

ROUTINE MAINTENANCE
FOR THE MONTH OF

DIAGNOSTIC DETAILS

* Prismatic covers di unit teknikal
blok. Inovasi.

- Membekal 2"x4" prismatic covers
untuk lampu di bangunan MPC

MATERIAL USED

LUBRICATE

- 15 CONDENSER FAN - FAN MOTOR
- 16 EVAPORATOR FAN - FAN MOTOR

OBSERVE

- 17 OPERATING SOUNDS - NORMAL
- 18 OPERATING SOUNDS - ABNORMAL
- 19 LOG OPERATION OF MACHINE
- 20 CHECK DAILY OPERATION LOG

Authorised Signature

CUSTOMER SIGNATURE (SIGN & CHOP)